

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventor(s): RALEIGH

Assignee: Cisco Technology, Inc.

Patent No: 6,144,711

Issue Date: November, 7, 2000

Application No.: 08/921,633

Filed: August 27, 1997

Title: SPATIO-TEMPORAL PROCESSING FOR  
COMMUNICATION*#27*  
Certificate  
MAY 18 2005  
of Correction**REQUEST FOR CERTIFICATE OF CORRECTIONS**

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

Dear Commissioner:

The above patent contains significant error(s) as indicated on the attached Certificate of Correction form (submitted in duplicate).

Such error(s) arose through the fault of the Patent and Trademark Office. It is requested that the certificate be issued at no cost to the applicant.

However, if it is determined that the error(s) arose through the fault of applicant(s), please note that such error is of clerical error or minor nature and occurred in good faith and therefore issuance of the certificate of Correction is respectfully requested. The Commissioner is authorized to charge Deposit Account No. 50-0292 any required fee. A duplicate of this request is attached.

Such error(s) arose through the fault of applicant(s). A credit card charge form for the fee is enclosed. Each such error is of clerical error or minor nature and occurred in good faith and therefore issuance of the certificate of Correction is respectfully requested.

05/17/2005 HVUONG1 00000020 6144711

01 FC:1811

100.00 OP

**Certificate of Mailing under 37 CFR 1.8**

I hereby certify that this response is being deposited with the United States Postal Service as first class mail in an envelope addressed to the Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450 on.

Date: May 11, 2005Signed: Amy Drury  
Name: Amy Drury

Such error(s) specifically:


In the drawings, Sheet 16, FIG. 16, for unit 240, kindly change "One TSW per Bin" to --One RSW per Bin--.

The undersigned requests being contacted at (510) 547-3378 if there are any questions or clarifications, or if there are any problems with issuance of the Certificate of Correction.

Respectfully Submitted,

May 11, 2005

Date

  
Dov Rosenfeld, Reg. No. 38687  
Agent of Record.

Address for correspondence:

Dov Rosenfeld  
5507 College Avenue, Suite 2,  
Oakland, CA 94618  
Tel. (510)547-3378; Fax: (510) 291-2985

(Also Form PTO-1050)

**UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION****PATENT NO : 6,144,711****DATED : November 7, 2000****INVENTOR(S) : RALEIGH**

It is certified that an error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

In the drawings, Sheet 24, FIG. 24, in the block having reference numeral 300, the annotation "Symbol Sequence Demodulator" should be changed to --Symbol Sequence Demultiplexor--.

MAILING ADDRESS OF SENDER (Atty/Agent of Record):

Dov Rosenfeld, Reg. No. 38687  
5507 College Avenue, Suite 2  
Oakland, CA 94618PATENT NO: 6,144,711  
No. of additional copies

(Also Form PTO-1050)

**UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION****PATENT NO : 6,144,711****DATED : November 7, 2000****INVENTOR(S) : RALEIGH**

It is certified that an error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

In the drawings, Sheet 16, FIG. 16, for unit 240, kindly change "One TSW per Bin" to --One RSW per Bin--.

MAILING ADDRESS OF SENDER (Atty/Agent of Record):

Dov Rosenfeld, Reg. No. 38687  
5507 College Avenue, Suite 2  
Oakland, CA 94618PATENT NO: 6,144,711  
No. of additional copies \_\_\_\_\_